


SonicTC FRF Analysis Report

Product Kunde => Fahrzeugtyp => Bremsbelag 4711	Test Object Prüfobjekt 11	Material Bremsbelag	Drawing Number 13.2345-5421.1	Order Auftrag 1104
---	-------------------------------------	-------------------------------	---	------------------------------

Comment Hinweise zu Prüfeinstellungen, etc.	Station FRF Test	Frequency Resolution 2 Hz	System 1.0.0.0	 
---	----------------------------	-------------------------------------	--------------------------	---

Sensor Input Force1_086E80	Sensor Output MIC1_MI17	Created at 31.10.2023 18:00:53	Created by Admin	Characteristic FRF	Workflow FRF Analyse
--------------------------------------	-----------------------------------	--	----------------------------	------------------------------	--------------------------------



#	Hz	Pa/N	η
1	4464	5,1872	0,0013
2	5390	2,0243	0,0065
3	9470	15,8918	0,0035
4	10860	2,4645	0,0031
5	12554	2,4314	0,0149
6	14926	2,8214	0,0048
7	15506	12,6086	0,0033
8	16586	5,3043	0,0075